

3801 EAST MARGINAL WAY, SOUTH SEATTLE, WA 98134 PLANT OFFICE (206) 623-5596

June 9, 1987

Puget Sound Air Pollution Control Agency 200 W. Mercer Street Room 205 Seattle, Washington 98119-3958 Attention: Mr. V. Aguilar

Routine Inspection

Dear Mr. Aguilar:

With reference to your letter of May 27, please find this list of responses to the deficiencies listed. In addition please also find enclosures as invoice, purchase order requests and sketches detailing the ship unloader auger dust shrouds.

- 1. Bulk load out area: The cement hopper covers have been ordered, received and installed. See enclosed order request and invoice for six covers for our five hoppers plus one spare.
- 2. Inspection covers on conveyor: Shrouds have been made operable and open and close without leaving opening for emmissions. Where covers have been damaged or altered for maintenance purposes, new covers are being fabricated in our plant shop, and will be in place prior to next use.
- 3. North Dust Collector: Area is being cleaned by three plant employees and maintained and inspected by plant repair personnel, to determine if there is any potential for spills, other than chunks in the product, as was the cause of the spillage you observed. This is proceeding or has been completed, as of this writing.
- 4. Dock Side conveyor: Clean up of all loose cement has been completed and will be maintained in that condition during use. Conveyor covers have been inspected for cracks and checks and found to be in excellent condition, plecluding possible carry-around dust source as you pointed out.
- 5. Cement Dust Shoveled: There is now a dust cover strapped down to all hoppers in the terminal and on the dock. Any hopper used for shovelling has a cover strapped down except the front is pulled up enough for a shovel to enter and turn 180 degrees for dumping.
- 6. Ship Unloading Augers: Shroud design and dimensions have now been checked and approved. The steel, strip curtains and fastenings have been ordered and

Puget Sound Air Pollution Control Agency Mr. Aguilar Page Two 6/9/87

will be fabricated in our plant upon arrival in a couple of days. The shrouds will be installed and operational prior to next use. Please find above preliminary sketches and purchase request copies covering these materials to Bloch Steel T-90, Seattle Tarp T-91, John Perline T-93.

I hope the above is found to be within compliance as requested. If there are any further questions or comments, please advise.

Yours truly

Stan Webb

Terminal Manager

SW:wsh

cc: Mr. S. Brooks

TELEPHONE: (206) 624-9422 SEATTLE TARP CO.

INVOICE

9 14077

SOLDIO ASH GROVE CEMENT 3801 EAST MARGINAL SO SEATTLE, WA. 98134

5-27 1987

QUANTITY	DESCRIPTION		AMOUNT
6	- 60 X 60 (20144 NYLAN)		
256	COULTS WITH GRAMMETS ON		1
	12" CENTERS		į
	(0,49.50-la	129	715
		A. 2	3 4
	Ship To.	43:	20 9
	5900 W. MARGINAL S.W.		
	0		
	· Raph of	-	1
	Morall as 1		
	N5-28-0 / Sam (1/20)		
TLE TARP	PSAPCA		1

2122 W. Elmore satile, WA 98199 (206) 285-2819

HAY COVERS

GRAIN COVERS

ROPE

LADDERS

INDUSTRIAL COVERS

NETS RO

ROPE SPLICING

BURLAP

ITEM 1

VI 779545	DUE DATE 6-23-87
G.L.1 12-10-6200	320,96
MyLan Cove	AS.
GROSS AMOUNT	320.76
DISCOUNT	
NET AMOUNT	
P.O.1 7-65 GOO	DS REC'D 5-29-87
CHECKED BY WAS	

ASH	GROVE	CEMENT	WEST.	INC
AJII	CINOIL	CUILITI	nLJI,	LIIC.

ORDER REQUEST

	STATILE WA.
Quantity	Item Description
6.17	The second second second second second second
	TO THE STANDARD OF THE STANDAR
	SO & GOT WITH ARMINETS FATH 12" ALSO TOLL
	ちょうちょるといわれて、は、サード・ウェントをでいる。プロ
	NET 50
	FOR OUR TETAL
	+ 7184
	CONTRACTOR
For:	When Needed: 1 Care A R.C
Iniated By:	4

AGCS2M003459

CONFIDINING T-90

BLOCK STEEL 4580 COLORADO GEDER REQUEST

Supplier: SEATTLE, W.A. 98124 Phone: 763-0200Date: 6/9/87

		LARRY			
Quantity	Item Description	(ID-CC-)	WGT	PLAY	COST
IEA.	5/16" X 6" SHAFT	1018	ang -	TUE .	@\$4.50
100 YF	7	PON	244 LB	, FEIDAY	@ \$37323
ZEA.	2'-8" x 12'-7" x 1/2	4" PL, M.S,	685 -	WED.	@\$2500/co
ZEA.	1'-4" × 12'-7" × 1/2	4" PL. M.S.	343 "	Þ3	@41250/4
2 EA.	1'-9" x 12'-7" x V	4" PL. M.S.	450 -	bs.	@ \$ 16425/
1 EA.	2'-11" x A'-0" x y	4" PL. M.S.	119 -	м	@ \$ 43 AT/
100 4F	1/4 x1" FLAT BAR		85 4	FRIDAY	@ AbviseT
ACOEA.	PUNCH 9/32" DIA. H	OLES THRULT	EM52 *	7 TO N	LATCH,
	EACH 6" ON CENTE	ERS. LIRON	PUNCHE	SON	OFONE
	2" SIDE, FLAT BAT	2 PUNCHES	START	-@1"F1	ROM END
For:	SHIP UNLOADER H			n Needed:	Rust
	COVERS - PSAPC	A COMPLIANC	E		

Iniated By: Approved By:

CONFIRMING

PACIFIC INDUSTRIAL ORDER REQUEST

Supply Company, INC. Phone: 682-2100 Date: 6/9/87

SEATTLE, WASH.

GARY

Quantity	Item Description
LEA.	JET CHAIN HOIST STON CAP 115V 3ING, PH. \$19520 /EA.
	TO HOLST ADDED WEIGHT OF SHROUDS
	PLUS TAX
	NET 30
	FOB YOUR PLANT
For:	SHIP UNLOAD HOLD AUGER When Needed: RUSH
	SHROUD - PSAPCA COMPLIANCE 6/12/87

Iniated By: Welch

Approved By:

CONFIRMING

JOHN PERINE ORDER REQUEST


820 3. ADAMS
Supplier: SEATTLE, WA. Phone: 682-9755 Date: 6/9/87

MELESTERY

Quantity	Item Description
300 EA.	1/4" x 1/2" HEX HEAD CAPSCREWS NG. MS \$1.84/C
300 h	VA" FLAT WASHERS MS .70/c
300 -	1/4" LOCK WASHERS MS ,45/c
300 -	44" NUTS N.C46/C
100 "	3/4" FLAT WASHERS MS 8.75/C
	NET 30
	UPS-PPY. & CHE YOUR TRUCK
	PLUS TAX
For:	SHIP ENLOAPER HOLD AUGER When Needed: PUSH
	SHROUDS-PASAPCA COMPLIANCE

Iniated By: Walk

Approved By:



N,T.S.

